

ABSTRACT

WA-II-174

19th Century

Shingle Sided House

Hagerstown-Boonsboro Vicinity

private

This shingled house, probably of log construction is typical of many 19th and early 20th century dwellings which may be found in the mountainous areas of Maryland.

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Shingle Sided house

2 LOCATION

STREET & NUMBER

San Mar Road

CITY, TOWN

CONGRESSIONAL DISTRICT

☒ VICINITY OF Hagerstown-Boonsboro 6

STATE

Maryland

COUNTY

Washington

3 CLASSIFICATION

CATEGORY

☐ DISTRICT
☒ BUILDING(S)
☐ STRUCTURE
☐ SITE
☐ OBJECT

OWNERSHIP

☐ PUBLIC
☒ PRIVATE
☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS
☐ BEING CONSIDERED

STATUS

☒ OCCUPIED
☐ UNOCCUPIED
☐ WORK IN PROGRESS
ACCESSIBLE
☐ YES: RESTRICTED
☐ YES: UNRESTRICTED
☒ NO

PRESENT USE

☐ AGRICULTURE
☐ COMMERCIAL
☐ EDUCATIONAL
☐ ENTERTAINMENT
☐ GOVERNMENT
☐ INDUSTRIAL
☐ MILITARY
☐ MUSEUM
☐ PARK
☒ PRIVATE RESIDENCE
☐ RELIGIOUS
☐ SCIENTIFIC
☐ TRANSPORTATION
☐ OTHER**4 OWNER OF PROPERTY**

NAME

Ernest L. Koontz and Mary J. Koontz

Telephone #:

STREET & NUMBER

Route # 2, Box 290

CITY, TOWN

Boonsboro

VICINITY OF

STATE, zip code

Maryland 21740

5 LOCATION OF LEGAL DESCRIPTION

COURTHOUSE,

REGISTRY OF DEEDS, ETC.

Washington County Court House

Liber #: 630

Folio #: 280

STREET & NUMBER

West Washington Street

CITY, TOWN

Hagerstown

STATE

Maryland 21740

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION**CONDITION**

☒ EXCELLENT
☐ GOOD
☐ FAIR

☐ DETERIORATED
☐ RUINS
☐ UNEXPOSED

CHECK ONE

☐ UNALTERED
☒ ALTERED \leq 50%

CHECK ONE

☒ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This house is located on the east side of San Mar Road, south of Mt. Lena and southeast of Hagerstown in Washington County, Maryland. It stands on level ground and faces west. The structure is a one and a half story, three bay house presumably built of logs and resting on low stone foundations. To the rear extends a one and a half story, two bay wing also probably of log construction. The surface of the building is sheathed with red shingle siding.

Windows have two over two pane double hung sashes held within narrow frames. The main entrance is located in the central bay of the front or west wall. Most openings are trimmed with early 20th century flat topped architraves.

Asphalt shingles cover the roof. A concrete sheathed flue is located against the south end wall.

One story porches extend along the west and part of the north elevations.

The building appears to be in excellent condition and stands on a property containing about 11 acres.

CONTINUE ON SEPARATE SHEET IF NECESSARY

8 SIGNIFICANCE

| PERIOD | | AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW | | | |
|---|--|--|---|--|--|
| <input type="checkbox"/> PREHISTORIC | <input type="checkbox"/> ARCHEOLOGY-PREHISTORIC | <input type="checkbox"/> COMMUNITY PLANNING | <input type="checkbox"/> LANDSCAPE ARCHITECTURE | <input type="checkbox"/> RELIGION | |
| <input type="checkbox"/> 1400-1499 | <input type="checkbox"/> ARCHEOLOGY-HISTORIC | <input type="checkbox"/> CONSERVATION | <input type="checkbox"/> LAW | <input type="checkbox"/> SCIENCE | |
| <input type="checkbox"/> 1500-1599 | <input type="checkbox"/> AGRICULTURE | <input type="checkbox"/> ECONOMICS | <input type="checkbox"/> LITERATURE | <input type="checkbox"/> SCULPTURE | |
| <input type="checkbox"/> 1600-1699 | <input checked="" type="checkbox"/> ARCHITECTURE | <input type="checkbox"/> EDUCATION | <input type="checkbox"/> MILITARY | <input type="checkbox"/> SOCIAL/HUMANITARIAN | |
| <input type="checkbox"/> 1700-1799 | <input type="checkbox"/> ART | <input type="checkbox"/> ENGINEERING | <input type="checkbox"/> MUSIC | <input type="checkbox"/> THEATER | |
| <input checked="" type="checkbox"/> 1800-1899 | <input type="checkbox"/> COMMERCE | <input type="checkbox"/> EXPLORATION/SETTLEMENT | <input type="checkbox"/> PHILOSOPHY | <input type="checkbox"/> TRANSPORTATION | |
| <input type="checkbox"/> 1900- | <input type="checkbox"/> COMMUNICATIONS | <input type="checkbox"/> INDUSTRY | <input type="checkbox"/> POLITICS/GOVERNMENT | <input type="checkbox"/> OTHER (SPECIFY) | |
| | | <input type="checkbox"/> INVENTION | | | |

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

This shingled house, probably of log construction is typical of many 19th and early 20th century dwellings which may be found in the mountainous areas of Maryland. Its age is unknown from information available at present.

CONTINUE ON SEPARATE SHEET IF NECESSARY

MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATAACREAGE OF NOMINATED PROPERTY 11 acres

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Paula Stoner Dickey, Consultant

ORGANIZATION

Washington County Historical Sites Survey

DATE

March 1978

STREET & NUMBER

County Office Building, 33 West Washington Street

TELEPHONE

791-3065

CITY OR TOWN

Hagerstown

STATE

Maryland 21740

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438



WA-11-114

S.W.

100 1115

Shingle Sided House

San Mar Road

Hagerstown-Boonsboro Vicinity

PAUL R. STODOLSKI, DIRECTOR
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY



WA-11-174

N/L

Oct 1975

Shingle Sided House

San Mar Road

Hagerstown-Boonsboro Vicinity

J. SPENCER DITREY
CONSULTANT, WASHINGTON CO.
HISTORICAL SITES SURVEY